

LAB TOOLS > GLASSWARE

PYCNOMETER with THERMOMETER

Code : W013



• A pycnometer with a thermometer in engineering testing laboratories is used to measure the density or specific gravity of liquids, powders, or solids. The built-in thermometer allows for precise temperature control, ensuring accurate density measurements, as density can vary with temperature. This is essential in material characterization and quality control.

ORDERING INFORMATION

ltem	Code
PYCNOMETER with THERMOMETER - 25 ml	W013G025H
PYCNOMETER with THERMOMETER - 50 ml	W013G050H
PYCNOMETER with THERMOMETER - 100 ml	W013G100H